Project Narrative:

571-PA-2004, 38-DR-2005

It is proposed to remodel the interior of the existing office building, 7125 East Second Street, shown on Lots 22-24, into a classroom facility for the Arizona School of Real Estate and Business. The interior remodeling is proceeding under Tenant Improvement Plan Check # 4390-05. The two substandard buildings on Lots 19-21, adjacent to the south, have been raised and these lots are to be graded, paved, lighted and landscaped for parking.

The exterior of the existing old historic office building will be repaired as necessary and painted. The existing original doors and windows will also be repaired and painted. Colors are to be similar to existing but more "earthy", less orange and harsh. The landscaping in the front courtyard will remain: the four very large trees (2 olive and 2 ash) are to be cleaned and trimmed, overgrown shrubs replaced, lawn replanted and a new irrigation system installed. New landscape lighting will be installed to provide security and enhance the street appearance. The areas on north and south, presently in decomposed granite, will be landscaped with xeriscaping material. There is an existing wrought iron fence (about 2'-6" high) along Bishop Lane. The 2 ft. square block piers will be repaired (match building) and the rusted wrought iron fencing replaced to match existing. The existing asphalt paved parking on the west side of the building will be reduced in size, resurfaced and striped for 16 parking spaces.

The new parking lot to the south (Lots 19-21) will be regraded, paved and striped for about 41 cars. A 3 ft. masonry screen wall will be built on the street sides, stuccoed and painted to match the building. The existing 5 ft. sidewalk will be widened or removed an rebuilt to 6 ft wide except along the north part of the Bishop Lane face where the old historic wrought iron fence restricts the walk to 5 ft. Three masonry and wood shade pavilions are to be built; two on Bishop Lane and one on Second Street Six inch high concrete curbs will protect low water use landscaping (trees and shrubs) in islands, fingers, corners and along street faces. New 16 ft., light poles will be installed in the parking lot to provide security and circulation lighting. When not needed by the school (week end evenings) this lot can be made available to local businesses and galleries for valet parking. Open, public parking for neighborhood business is not anticipated.

Although the Quarter Section Map shows this property to be 4 lots (19 - 22) the real estate titles show 6 lots (19 - 24). In either case it is desired to combine all subject property into one lot. A Property Assemblage Application has been submitted.

In summary, the exterior details and character of the lovely old building and landscaping will remain substantially as is. The significant remodeling will be restricted to the interior. The south half of the property cleaned up and paved, lighted, landscaped, much needed off-street parking provided. Pedestrian enhancement and interest in the form of off-set sidewalks, shade structures and general landscaping will be provided on the Second Street and Bishop Lane faces.

Project Narrative:

571-PA-2004, 38-DR-2005

It is proposed to remodel the interior of the existing office building, 7125 East Second Street, shown on Lots 22-24, into a classroom facility for the Arizona School of Real Estate and Business. The interior remodeling is proceeding under Tenant Improvement Plan Check # 4390-05. The two substandard buildings on Lots 19-21, adjacent to the south, have been raised and these lots are to be graded, paved, lighted and landscaped for parking.


The exterior of the existing old historic office building will be repaired as necessary and painted. The existing original doors and windows will also be repaired and painted. Colors are to be similar to existing but more "earthy", less orange and harsh. The landscaping in the front courtyard will remain: the four very large trees (2 olive and 2 ash) are to be cleaned and trimmed, overgrown shrubs replaced, lawn replanted and a new irrigation system installed. New landscape lighting will be installed to provide security and enhance the street appearance. The areas on north and south, presently in decomposed granite, will be landscaped with xeriscaping material. There is an existing wrought iron fence (about 2'-6" high) along Bishop Lane. The 2 ft. square block piers will be repaired (match building) and the rusted wrought iron fencing replaced to match existing. The existing asphalt paved parking on the west side of the building will be reduced in size, resurfaced and striped for 16 parking spaces.

The new parking lot to the south (Lots 19-21) will be regraded, paved and striped for about 41 cars. A 3 ft. masonry screen wall will be built on the street sides, stuccoed and painted to match the building. The existing 5 ft. sidewalk will be widened or removed an rebuilt to 6 ft wide except along the north part of the Bishop Lane face where the old historic wrought iron fence restricts the walk to 5 ft. Three masonry and wood shade pavilions are to be built; two on Bishop Lane and one on Second Street Six inch high concrete curbs will protect low water use landscaping (trees and shrubs) in islands, fingers, corners and along street faces. New 16 ft., light poles will be installed in the parking lot to provide security and circulation lighting. When not needed by the school (week end evenings) this lot can be made available to local businesses and galleries for valet parking. Open, public parking for neighborhood business is not anticipated.

Although the Quarter Section Map shows this property to be 4 lots (19 - 22) the real estate titles show 6 lots (19 - 24). In either case it is desired to combine all subject property into one lot. A Property Assemblage Application has been submitted.

In summary, the exterior details and character of the lovely old building and landscaping will remain substantially as is. The significant remodeling will be restricted to the interior. The south half of the property cleaned up and paved, lighted, landscaped, much needed off-street parking provided. Pedestrian enhancement and interest in the form of off-set sidewalks, shade structures and general landscaping will be provided on the Second Street and Bishop Lane faces.







38-DR-2005 09/02/05

FOR ARIZONA SCHOOL OF REAL ESTATE & BUSINESS BY W G BISHOP LANE PROPERTIES, LLC

-02 00



38-DR-2005 09/02/05



 \odot

3

3

NEW LOW MATER USE PLANTING SEASONAL PLOYERS

3 FT, HIGH MASCHINY SOMEON SMLES AT ANY COME COMPRESSORS, ETVICCES AND FRONT TO MAYOR SIGNORS, OF IGST MR TUMBLE WIED?



- The tree congry, when fully grown, it computed to be 30' Ø for Sweet Arents, 35'Ø for Olive and Pole Breet, 30' Ø for Manguita.
- 4. There are 7 existing sine, 5 mappulse and 5 polic winds from an Bishop Lanz. There is no existing demonst free species or End Street, one large poin verile, two existingties of undeformined species or last condition and ${\bf a}$ number of pole vents a black away at the But Center. The plant than silver with some manquite and pair Break on Bishop and pain oreas demonstra



REMODEL CLASSROOMS &

PARKING
TIES E 200 STREET, SCOTTEDALE, ARROWN
AMERICAN STREET, ST. OF A PERSON LAND PROPERTY, MAY

571-PA-2004 38-DR-2005

14 Mile 06 ANDS 1 . 70

REMODEL 7125 E. 2ND


BUSINESS , LLC

B B ES.

SCHOOL OF

ARIZONA S

38-DR-2005 09/02/05



	KEY TO NOTES			-	
0	EXETTING BLAUTING BENEVERS INTERIOR EXTERIOR TO REMAIN SHEET WITHAUT AS B. REPAIR AND REPAIRT BYLCOD, DE CEIP ME TILMELE WIELD.	0	EXCEPTING ABPHALT PAYING TO BE REPAIRED, RESUMPACED AND STRIPED	(3)	TOTAL PART TO MADE
		0	NEW ADPHALT PAYING.	6	
E	COSTING VENTION, OURS AND OUTTON TO REMAIN	99	PARTED PARKING STREET	8	
0	EXISTING BOLL-CURB AND		THE PT & SHIPT VAN ADDRESSED.		
23	GUTTER TO FEMAN	(6)	AFT A 18YT, DISABLED PARKING.	3	HE'S CONCRETE HALK FROM BEAUE OF PARKING TO EXPENSE WHILK MAXIMUM SLOPE TO IN OMECTION OF THAYSE.
©	EDEWAY, TO REMAIN	1	SIGNALIZO PARIONO SIGN DOMINIO ET MICAROL		
0	REMOVE EXERTING S.FT CONCRETE SIDEWALK	0	SOFT DRIVEWEY OFF OF	8	HERRYS FT, JACH FANKING UST
1	NEW 6 FT. CONCRETE SCHWALK	-	SCOMSONT MARRIES	120	BECURITY LIGHT STANGARDS.
ŏ	AGO 1'4" CONCRETE TO EXETHE 17T, BEENALK TO MARE EVE	0	PHENNIATRICAL CONCRETE	66	SOLLARDS & FIG 4 5
0	EXECUTE CONCRETE ON SITE	0	EXTREME CONCRETY	@	BICYCLÉ PHINNIS BACK
Ξ.	WALKWAYS, TO REMAIN	3	10 FY SQUARE EXPOSED		
•	CONTINUE OF A MACCAST SCHOOL OF THE PARTY SCHO	•	ADDRESSATE SUSHIT YEXTURE; CONCRETE SUAR, OUT OUT AS REQUIRED TO ACCOMMODATE SECTIONS CLASS TREES.		
		0	FILL IN EXISTING NAMEON PLANTING DUTCOUTS BY EXISTING MAJORITH TO MATCH.		
С	NEW 3 FT, SARDING SCHEEN WALK WITH 2 FT, SQ, X, P, A' PRINS STUDIOL AND PART TO MATEN THE SUILCING OF YOUR MA	0	WORLDWAT DIGH BY SEPARATE WORK WORK		
•	"CLAMES WAILTS MADDRITY PRINT, DE MADE PRINT, DE LA PLAT HODA MONT MODELLE MADE LA PLAT HODA MONT MADE PART HODA MONT MADE PART HODA MODELLE MADE PART HODA MODELLE MADE PART HODA MODELLE MADE MADE PART HODAS MADE PART HODA	8	AND BE RESTORED TO TENANS		
		0	EXECUTED FURN TO BE REMOVED AND REPLACED WITH JUNE WATER USE PLANTING		
		(4)	MINION WATER USE PLANTING.		
		ĕ	BEABONS FLOWERS / T/		
6	ABIN 4 PT CONCRETE WALKINGY IN SERVICE AREAS	E	3 FT HIGH MASONITY SCREEN MALS AT AS CONE CONVESSORS. STUDOO AND PARK TO MATCH SUIL DWG. OF ONE AND TUNNELS WEEL?		
()	EXECUTION ASSPHALL PARAMES TO SE SEMENSED AND REPUACED WITH LOW WATER-LISE LANCECAPING				



- 2. A minimum of one half of the treat to be planted shall be Mathewstreen, defined as having a 10 to 12 feat high? and 2 such truch calling for everage 1° saligner truck for martiple truch treat one, depending on species 30° or 16° has minimum to matter behalfly statedonts for anywher saligner. (Scottaleia Zoning Cada, Art. SC, 2.00)
- It is true samply, when high grows, is computed to be 35' if for Sweet Missin, 25' if for Since and Francisco, 35' if for Massachia.
- 5. There are T existing alive, 5 mesquite and 3 pole verse trivial on Bishop Loss. There is no existing desirent five species of 2nd 5freet, are large pole verds, two sucception of undetermined species in bad condition and a member of pole words a block ower at the Bus Center. The plans those clies with same descuit? And pole breat on Bloker and pole breat demonstring



REMODEL CLASSROOMS &

PARKING
7128 E. DAN STREET, SCOTTENALE, ARGON # # P Camper LANS Succession, 656

571-PA-2004 38-DR-2005

REMODEL 7125 E. 2ND ARIZONA I 1 1 20


PARKING E. ARIZONA

BUSINESS

8 E

SCHOOL (

CLASSROOMS & F
STREET, SCOTTSDALE,
FOR
HOOL OF REAL ESTATE &
BISHOP LANE PROPERTIES



PLA Nacale 1/8" # 190"


CLASSROOMS & PARKING STREET, SCOTTSDALE, ARIZONA BUSINESS REMODEL 7125 E. 2ND S S

TOM DENNY, ARCHITECTI 1631 W. Caralina Dr. 1631 W. Caralina Dr. Proenty, A.Z. Bands Pr. 600, 814 - 480 tolerny/Ploops and

7D 10 AUG 05

RY M & BORNEY LAND PROFESSION, SAID

09/02/05



→ N-- C:=-

PLAN SCALE 1/8" - 1'0"

371 PA-2004 18 DR-2005

AT W G MINNEY LANG PROPERTIES, LLC.

09/02/05